


U.S. DEPARTMENT OF THE INTERIOR U.S. GEOLOGICAL SURVEY



A Product of the National Water-Quality Assessment Program Great Salt Lake Basins Study Unit

Map showing location; logs showing lithology, natural gamma radiation count, and electrical conductivity of the basin-fill deposits; and hydrographs showing water-level fluctuations from September 1999 to July 2001 for monitoring wells installed in recently developed residential/commercial areas, Salt Lake Valley, Utah

Susan A. Thiros 2003

Water-Resources Investigations Report 03–4029 Well logs and water-level hydrographs, Salt Lake Valley, Utah-PLATE 1

Thiros, Susan A., 2003, Hydrogeology of shallow basin-fill deposits in areas of Salt Lake Valley, Salt Lake County, Utah

Printed on recycled paper